



[TO BE PRINTED ON COMPANY HEADED PAPER]

Please find attached documentation which demonstrate the compliance of the relevant refill container with the provisions of Directive 2014/40/EU of 3 April 2014, and Commission Decision 2016/586 of 14 April 2016 related to the opening and refilling of electronic cigarettes.

1. **Annex I** – a technical drawing and a series of photographs depicting the opening of the Guardian tank. This drawing shows that the space designed for refilling has a width of 1.85mm.
2. **Annex II** – relevant pages of the instruction manual (in English) that provide instructions to customers as to how to open and refill the tank unit. These instructions clearly specify that the nozzle width of the refill container should not exceed the width of the space designed for refilling.

Please also see our leaflet file contained elsewhere in this notification, which contains the relevant opening/refill instructions, including diagrams, as required by both the Directive and the Decision.

## Annex I – technical drawing and photograph of refill mechanism

	<p>This image represents a to-scale technical drawing of the <i>Guardian</i> tank with the top-cap removed from a 'birds-eye' angle. The image shows that this width of the gap for refilling is 1.85mm (being that the outside diameter is 8.35mm and the inside diameter is 6.5mm; the width of the opening is <math>8.35\text{mm} - 6.5\text{mm} = 1.85\text{mm}</math>).</p>
	<p>This image is a photograph of the <i>Guardian</i> tank with the top cap removed from a 'birds eye' angle. It is included in order to clarify what the technical drawing above means.</p>

## Annex II – instruction leaflet for Guardian tank

